

# FORD PERFORMANCE




**January 11, 2025**

## **Technical Service Bulletin – 20**

### **Master Cylinder Fitting Revision**

Issue: An improper fitting was used during build of cars 1-40

- The improper fitting can be identified in the photo below.



Action:

- Replace fittings (2 places) with the Ford Performance part number 9183-MTN.