

# FORD PERFORMANCE



January 9, 2025

## Technical Service Bulletin – 32

### ABS Pressure Sensor Fitting Update

Issue: An improper fitting was used during build on some units, 1-40.

- The improper fitting can be identified as Fore # 200103.
- If your vehicle was built with an Earl's fitting, no change is required.



Action:

- Replace all Fore fittings with the Ford Performance part number LCR-DH-BOSCH-ADP.

