## FORDPERFORMANCE





March 10, 2025

### Technical Service Bulletin – 37a

#### **Mustang Dark Horse R ABS Updates**

Please update in the following order:

- 1. RaceABS Software
- 2. M5 ABS Software
- 3. Calibration File
- 4. DTC Code Definitions

#### Action 1: Please update to latest version of RaceABS software

- Latest version: <u>3.5.4.21</u>
  - Additional link: <u>https://www.bosch-</u> <u>motorsport.com/content/downloads/Raceparts/en-</u> <u>GB/381092107.html</u>

#### Action 2: Verify M5 ABS Software

- Open RaceABS and connect to vehicle
- Navigate to the 'ECU Info' page, and verify that:
  - o 08.03.00.00.00 is stated in the 'Software Version' box

Ecu Info	nfo Testing Function Switches								
Software Number	96242	Software Version	08.03.00.00.00.00	gnition Cycle 00-85 Counter	App Name	FordDHR_v02	Build Date	2/28/2025 4:30:29 PM	

If 08.03.00.00.00 is not stated in the 'Software Version' box, please contact Ford Performance to arrange an appropriate time to update your M5 ABS module to the latest software.



#### Action 3: ABS Calibration

- Open RaceABS and connect to vehicle
- Navigate to the 'ECU Info' page, and verify that:
  - *FordDHR\_v02* is stated in the 'App Name' box

Ecu Info	Testing	Function Switches								
Software Number	9624	12	Software Version	08.03.00.00.00.00	Ignition Cycle Counter	00-85	App Name	FordDHR_v02	Build Date	2/28/2025 4:30:29 PM

• If *FordDHR\_v02* is not stated in the 'App Name' box, navigate to the 'Vehicle Data' page, and select [import] in the top left of the page.

٢								
🔳 🗸 🛛 Properti	es Security	Layout						
Diagnostic Errors	Salmport 📔	Export						
₽ Logs								
	Import	Export						
VehicleData Ecu Info Testing Function Switches								
✓ VehicleDataABS								

[must have Software Version 08.03.00.00.00.00]

Navigate to and select this file:

```
'RaceAbs.Export_FordDHR_v02_BL08.03.abs'
```

```
RaceAbs.Export_Ford
DHR v02 BL08.03.abs
```

- This file is available in the Owner's Information area on the Dark Horse R Mustang Challenge Site
- <u>https://performance.ford.com/motorsport/mustang-</u> <u>challenge/competitor-info</u>
- This will update your Bosch M5 ABS Module to the *FordDHR\_v02* calibration.

If software version 08.00.00.00.00.00 is present – a different calibration file is required.

• Follow the procedure above, but using calibration file 'RaceAbs.Export\_FordDHR\_v02\_BL08.00.abs'

## FORDPERFORMANCE

- This file is available in the Owner's Information area on the Dark Horse R Mustang Challenge Site
- <u>https://performance.ford.com/motorsport/mustang-challenge/competitor-info</u>

# Action 4: Verify the DTC Code definitions and RaceABS Software are properly linked

- Not having the proper DTC Code Definition .XML text file linked to RaceABS would make all DTC Codes meaningless
- Open RaceABS and connect to vehicle
- Navigate to 'Ecu Info'
  - If the incorrect DTC code Definition .XML is linked, the orange error statement below will occur:

ehideData Ecu Info Testing Function Switches										
Errors										
Softw Num	96242 ber	Software 08.03.00.00 Version	0.00.00 Ignition Cycle Counter	00-2A	App Name FordDHR_v01	Build Date 12/	13/2024 8:37:58 AI	Clear Faults Save Faults		
Attention no	Attention not all fault entries are translated in text format. Please choose the correct diagnostic errors file for the software. For more information please look into latest ABS/EBS manual. Diagnostic Error File (V96242/08.02.00.00.00.00)									
Error1		Error2		Error3		Error4				
FPath : 00-	-00 - FType : 0	FPath : 00-0	0 - FType : 0	FPath : 00-0	10 - FType : 0	FPath : 00-0	00 - FType : 0			
FPath	00-00	FPath	00-00	FPath	00-00	FPath	00-00			
FType	0	FType	0	FType	0	FType	0			
Occurences	<b>0</b>	Occurences	0	Occurences	0	Occurences	0			
First Pcc	00-00	First Pcc	00-00	First Pcc	00-00	First Pcc	00-00			
Recent Pcc	00-00	Recent Pcc	00-00	Recent Pcc	00-00	Recent Pcc	00-00			
Debug0	00-00-00	Debug0	00-00-00	Debug0	00-00-00	Debug0	00-00-00			
Debug1	00-00-00	Debug1	00-00-00	Debug1	00-00-00	Debug1	00-00-00			
Operating Hour Mete	0:0 h:m	Operating Hour Meter	0:0 h:m	Operating Hour Meter	0:0 h:m	Operating Hour Meter	0:0 h:m	<b>v</b>		

• Select [Diagnostic Errors]

۲								
Properti	es Secur	ity Layout						
Diagnostic Errors	😪 Import	Export						
Ē Logs								
	Import	Evport						
import Export								
VehicleData Ecu Info Testing Function Switches								
√VehicleDataABS								



- Navigate to and select this file:
  - Patch: "C:\Program Files (x86)\Bosch
     Motorsport\RaceAbs\DiagFiles\UDS\08.03.00.00\TKWINX\_FAILUREM
     EMORYDESCRIPTION\_BB96242.XML"



NOTE: This file should be in your RaceABS folder structure similar to above that was designated when installing the new RaceABS software 3.5.4.21. Otherwise, it will be posted to the Mustang Challenge Owner's Information area.

• You should see "Result: Diagnostic file is linked"

۲							
Propertie	s Securi	ity Layout					
Diagnostic Errors	😪 Import	Export	Result : Diagnostic file is linked				
	Import	Export					
VehicleData Ecu Info	Testing F	unction Switches					
√VehicleDataABS							

- RaceABS is now linked to the proper DTC Code definitions file and the orange error will disappear. It's recommended to do a key cycle after this step
- The .XML text file may be opened to read the details and descriptions of ABS DTC Codes when trying to diagnose errors