

# FORD PERFORMANCE



**January 10, 2025**

## **Technical Service Bulletin – 19**

### **Optional Change**

#### **Rear Toe Link Revision**

Purpose: The rear toe link assembly, part number DHR-TOE-LINK-ASSY has changed to DHR-TOE-LINK-ASSY-R2. The FK Bearing rod end has been revised to a preloaded Teflon lined bearing.

This applies to cars with serial numbers 1-40.

- The original rod end part number from FK is JFXL10. It has no preload.
- The replacement rod end part number from FK is JFXL10T, F1 fit.



FK Bearings

865 West Queen Street

Southington, CT 06489

800-662-4003

860-628-0463 Fax

[sales@fkrodends.com](mailto:sales@fkrodends.com)

Monday-Friday 8:00am-5:30pm EST