


August 12th, 2024

Technical Service Bulletin – 13

Shifter Linkage Inspection

Issue: Some vehicles were built without a shifter linkage clip installed, as shown in the photo below.



Action: Install clip per photo below. If a clip is required, please contact Watson Engineering, Inc. at the following email address: sales@watsonracing.com

